


TOWN OF SOUTH PALM BEACH TOWN HALL'S CURRENT CONDITION

As of 5/04/2022






BROKEN LIGHT FIXTURES INSIDE TOWN HALL OFFICES




PBSO AND TOWN STAFF KITCHEN






What is supposed to be Town Hall attic window





side wall by entrance
to Town's Fire Bay



Entrance to Town's Fire Bay





Cracks on Council
Chambers outside wall and
maintenance room



Side staircase by Council Chambers












SIDE STAIRCASE BY THE COUNCIL CHAMBERS




Cracks on Council
Chambers outside wall
and maintenance room





Building Separating by
Sgt. Garrison's Office






South side of Town Hall -
cracks on the outside wall




Town Hall entrance -
cracks on the outside wall







Town Hall entrance -
cracks on the outside wall




Town Hall entrance -
Rusted railings











WATER DAMAGE



MAINTENANCE ROOM CEILING




MAINTENANCE ROOM CEILING





MAINTENANCE ROOM



MAINTENANCE ROOM






ENTRANCE TO
MAINTENANCE ROOM



ENTIRE SUPPLY ROOM HAS
EXTENSIVE MOLD





TOOL ROOM FLOOR INSIDE
TOWN'S FIRE BAY





TOOL ROOM CEILING, AND SIDE WALL HAS NO
INSULATION AND WHEN IT RAINS OUTSIDE IT
ALSO RAINS INSIDE



TOOL ROOM CEILING, NO INSULATION AND LIGHT FIXTURE HANGING BY A CHAIN




TOOL ROOM INSIDE WALL SEPARATING





ONE OF MANY BROKEN LIGHT SWITCHES




TOWN TELEPHONE AND INTERNET CABLES




TOWN'S TELEPHONE AND
INTERNET CABLES



TOWN'S TELEPHONE AND
INTERNET CABLE ROOM



TELEPHONE AND
INTERNET CABLES





UPSTAIRS -
A/C ROOM / PBSO LOCKERS /
STORAGE / CLOSET



UPSTAIRS -
A/C ROOM / PBSO LOCKERS /
STORAGE / CLOSET



**UPSTAIRS -
MISSING CONCRETE FLOOR**



**UPSTAIRS RECORDS ROOM ENTRANCE
MISSING CONCRETE FLOOR**




UPSTAIRS RECORDS ROOM –
A/C LINES AND BROKEN LIGHT FIXTURE



UPSTAIRS RECORDS ROOM –
TOWN SERVER IS RIGHT NEXT TO TWO (2) A/C UNITS


UPSTAIRS RECORDS ROOM -
TOWN SERVER IS RIGHT NEXT TO TWO (2) A/C UNITS





SIDE STAIRCASE FROM BY THE RECORDS ROOM
AND TOWN COUNCIL CHAMBERS





**VIDEO:
RAINING INSIDE SGT. GARRISON'S OFFICE**

